

Patrón (Standard)	UBP (UUT)	Error (Error)	Exactitud (Accuracy)	Incertidumbre (Uncertainty)	
1000 RPM	1000 RPM	0 RPM	± 2 RPM	±	5.8E+01 RPM
1500 RPM	1500 RPM	0 RPM	± 2 RPM	±	5.8E+01 RPM
2000 RPM	2000 RPM	0 RPM	± 2 RPM	±	5.8E+01 RPM
2500 RPM	2500 RPM	0 RPM	± 2 RPM	±	5.8E+01 RPM
3000 RPM	3000 RPM	0 RPM	± 2 RPM	±	5.8E+01 RPM